### **KONSUIL**

# ACCEPTANCE TEST & CERTIFIED FOR INDONESIA ELECTRICAL INSTALLATION

**Mulianto Gultom** 



#### **Maps of KONSUIL Representative Office**






### Number of Inspector

- Competent inspector : 1.828 people
- Administration staffs & management level: 195 People






#### **Scope of Works**





## Improvement of Ease of Doing Business (EoDB) Indonesia 2018 GETTING ELECTRICITY




Source: limited meeting of EoDB - March 2017

Brunei Darussalam (21)
Procedure : 4 steps
Duration : 35 days
Cost : 54,2% of income per capita

Best
Practice







#### **Duration**

Time Efficiency

One Way Service

1	Current Condition	Days
1	Request & publication of Acceptance Test & Certified	7
	Request of new electricity connection	9
	External inspection	1
	Construction work	40
	Electricity connection	3
		59


EoDB 2018	Days
Request of new electricity connection & publication of Acceptance Test & Certified	1
Installation inspection	3
Construction work & Electricity connection	21
	25

Source: www.pln.co.id



#### **One Way Service**

## Notifications of connection installment cost & Information of Chosen Technical Inspection Body



Source: www.pln.co.id



#### **Project Goals**

Regulator

As per the rule that the age of the installation o 15 years, should be reexamined

Technical Inspection
Body – Low Voltage

Customer

distributed

The price of protection tools is affordable and the distribution is evenly

By One Way Service, Target EODB – WB

**Getting electricity from** ratings 49 become 25

Equipment Provider
Handling counterfeit
products seriously



# TERIMA KASIH THANK YOU

MERCI
fisuel